Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 7 02 92 b 30252		
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.		
Date of Maintenance: 7-23-24 Property ID #:		
Property Address: Street Address	MY	Gerry Morrise MN 55017
Property Owner Name: PRuiz & Deboil wright		
Maintenance Perform	ed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	OR	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Se_ No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: So No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In Yes No Cover Damaged: Yes No Tank #2: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Tank #3: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Tank #4: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Pump Tank: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No		
Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location		
Other remarks or Concerns:		
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature:		

