

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed | | | | | |
|---|--------------------------|---|---------------------|--------------------|-------------------|
| prior to performing maintenance activities and remain on-site for the duration of the maintenance activity. | | | | | |
| Date of Maintenance: | 5/17/16 Reason | for Maintenance: | ROUTIN | E | |
| Property Address: 15 | 45 QUINLAN | AVE S F | roperty Owner's N | ame: RON THU | RINGER |
| Municipality: ST. CRO | DIX BEACH ZIP: 550 | 43 Property Ide | ntification Number: | | |
| | : h5674d0635N | | | | 715 |
| | Deformed | Tank Meas | urement (must be | completed if tanks | NOT pumped) |
| Maintenance Performed | | | | | |
| Tank(s) Pumped | | Liquid Level of Tank in | | | |
| ☐ Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No (if no provide measurements) = % Slud | | | ım Tar | nks must be pumped | if 25% or greater |
| 1. Access used to remove septage: Maintenance Hole Other (enter authorization code) NO MANHOLE COVERS 2. Were all covers securely replaced? Yes □ No | | | | | |
| | | | | | |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | |
| • | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes ✓ No | ☐ Yes ☒No | ☐ Yes ÆNo | |
| | Septic/Holding Tank #2 | ☐ Yes ⊠No | ☐ Yes ☒No | ☐ Yes ☒No | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| 4. How many gallons | of septage were removed? | • | | | |
| Tank #1 (20) gal Tank #2 (60) gal Pretreatment tank gal Pump Tank gal | | | | | gal |
| 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns. | | | | | |
| | 1. | | | | |
| | | | | | |