## **Subsurface Sewage Treatment System Maintenance Permit**

Property/Owner Information Permit #: 970942-25633	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 7-9-24 Property ID #:  Property Address: 2 1017 Meglow Brook City Scandia MN 55-073  Street Address City State Zip	
Property Owner Name: Mark Beckman	
☐ Emergency ☐ Home Sale	e and Scum Measured: (must be completed if tanks NOT pumped) d Level of Tank:in Sludge Level:in
<ul><li>☑ Routine/Maintenance</li><li>☐ Compliance Inspection</li><li>Sludg</li></ul>	Level:in e+Scum/Liquid Levelx100=%Sludge & Scum s must be Pumped if 25% or greater
Were all covers securely replaced Yes No If No, Explain:  Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit  Tank #1:   Yes    No Verification Method Used:    Uis    A    Gallons Removed:    500	
Maintainer Information  Maintainer Name: Ross Sewer Service, Inc Maintainer Signature:  Maintainer Address: 9288 county Rd. 5 NE North Branch, MN 55056  Phone Number: 651-674-4349  License Number: L3448  I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the Research observations, or directly supervised others in the performance of this job.	

PUBLIC Heshington County

Maintenance activities must be reported to the Department within 90 days