

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit n	nust be completed	
<u>prior</u> to perfor	ming maintenance activit	ies and remain on	-site for the durat	ion of the maintenar	nce activity.	
Date of Maintenance:	7,	for Maintenance:				
Property Address:	3970 55th S	+N I	Property Owner's N	lame: Rich	Springsor.	
Municipality: Lak	Elmo ZIP: 550	Property Ide	ntification Number	:		
Maintenance Permit N	o: e487h0671	Maintainer Name ar	nd License No.	Mexer G1	5	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced? A Yes of tank leakage from a sep ged, cracked, or structur	otic, holding, preti			ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes XNo	☐ Yes ☑No	Ų Yes ⊅No		
	Septic/Holding Tank #2	☐ Yes 🗷 No	☐ Yes ☒No	☐ Yes <b>(</b> No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 /500	gal Tank #2 1000	_gal Pretreatmen	t tankg	gal Pump Tank	gal	
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.	