Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: v 5 6 6 1 3 6 6 10	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 1/30/2024 Property ID #:	
Property Address: 15979 Settley W. Aug. City State Zip	
Property Owner Name:	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced → Yes □ No If No, Explain:	
Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: ☐ Yes ☐ No Verification Method Used: ☐ Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed:	
Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Pump Tank: Yes No Verification Method Used: Gallons Removed: 350 Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Waste Disposal Method: Treatment plant Land Apply: Location Other remarks or Concerns:	
302 101 2002	
supervised others in the performance of this job.	



Maintenance activities must be reported to the Department within 90 days.