## **Subsurface Sewage Treatment System Maintenance Permit**

Property/Owner Information Permit #: 67874W2013	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: Property ID #:	
Property Address: 23510 Manning Circle City State Zip	
Property Owner Name: Carol Kushke	
Maintenance Performed	
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scum  Tanks must be Pumped if 25% or greater
Maintenance Information  Access used to remove septage: Maintenance Hole Other (enter authorization code)  Were all covers securely replaced Yes \_No \ If No, Explain:  Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit	
Tank #1: ☐ Yes ☑ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☑ No Leaking In ☐ Yes ☑ No Cover Damaged: ☐ Yes ☑ No Tank #2: ☐ Yes ☐ No Verification Method Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #3:□Yes □ No Verification Method Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No  Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed:	
Tank #4: □Yes □ No Verification Method Used: Gallons Removed: Leaking Out: □Yes □No Leaking In: □ Yes □ No Cover Damaged: □Yes □ No	
Pump Tank: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location	
Other remarks or Concerns:	
Maintainer Information  Maintainer Name: Olson's Sewer Service Inc.  Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025  Phone Number: 651-464-2082  License Number: L216	
I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.  Maintenance activities must be reported to the Department within 90 days.	



