## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: h \$9916 361036		
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.		
Date of Maintenance: Y-/4-24		Property ID #:
Property Address: 13/75 500 Street Address	d View A	City State Zip
Property Owner Name: Jody Hahn		
Maintenance Perform	ed	
Were all covers securely replaced? Is the tank designed as a leaky? Ex. Se	Liquid I Scum L Sludge- Tanks n Tanks n Maintenance H Yes No If N	and Scum Measured: (must be completed if tanks NOT pumped)  Level of Tank:in Sludge Level:in  evel:in  +Scum/Liquid Levelx100=%Sludge & Scul  must be Pumped if 25% or greater  Hole Other (enter authorization code)  No, Explain:  esspool drywell leaching pit  Gallons Removed:
Leaking Out: ☐ Yes ☐ 40 Leaking In ☐ Y	es⊠¶o Co	over Damaged: Yes XIO
	nod Used:	Gallons Removed: / (2)
Tank #3:□Yes □ No Verification Method Used: Gallons Removed: Leaking Out:□Yes□No Leaking In:□Yes□No Cover Damaged:□Yes□No		
Tank #4: Yes No Verification Method Used: Gallons Removed:		
Leaking Out: ☐ Yes ☐ No Leaking In: ☐		
Pump Tank: Yes No Verification N		
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Y		
Other remarks or Concerns:	plant 🗌 Lan	d Apply: Location
	e Inc. Forest Lake, I nse Number: STS Maintainer t	L216 that I personally conducted the work and made the observations, or directly

