

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
Date of Maintenance:	6/7/16 Reason f	or Maintenance: _	ROUTINE	•		
Property Address:	30 20th ST.	Cr. N. P	roperty Owner's Na	me: JERRY	JUNKER	
	ELMO ZIP: 550					
	1656/1536 M					
maintenance Fermit No.	Y6361 N1336 M	amediter name an	a Electise Not meye			
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
✓ Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no	provide measurements)	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? Yes \(\subseteq \) No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
_	Tank	Leaking Out	Leaking In	Cover Damage		
<u>-</u>	Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes ⊠No	☐ Yes 🖎 Yo		
S	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
F	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
<u>.</u>	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of	f septage were removed?					
Tank #1 1500	gal Tank #2	gal Pretreatment	tankga	al Pump Tank	gal	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
					19	
6. Location of septage disposal: St Paul WTP						