Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information	Permit #: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 8/16/24	Property ID #:
Property Address: 22030 Kink M Street Address	Scandia MN 55073 City State Zip
Property Owner Name:	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm A Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Other: Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced Yes No f No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: Yes No Verification Method Used: Gallons Removed: O25 Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes Yes Yes No Verification Method Used: Gallons Removed: O25 Leaking Out: Yes No No No Leaking In: Yes No Cover Damaged: Yes Yes No No Yes No Cover Damaged: Yes No Yes No Tank #3: Yes No No Nerification Method Used: Gallons Removed: Leaking Out: Yes No No No No Yes No No No No No No No N	
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature: Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216	
I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintenance activities must be reported to the Department within 90 days.	

