## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Informati	On Permit #: 7 (889) m 3(a)c 17
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 8/23/24	Property ID #:
	N Marine MN 85097 City State Zip
Property Owner Name: Scott Traen	
Maintenance Performed	
☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:i  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scu
Maintenance Information	
Access used to remove septage: Maintenance Hole Other (enter authorization code)  Were all covers securely replaced24 Yes \Box No If No, Explain:	
Is the tank designed as a leaky? Ex. Seepage	
Leaking Out: ☐ Yes No Leaking In ☐ Yes	ed: Visual Gallons Removed: 1200
	ed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	No. Cover Damaged: DVos DNo.
	ed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
Tank #4: ☐Yes ☐ No Verification Method Us	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
	Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ I	
Waste Disposal Method Treatment plant ☐ Land Apply: Location North Branch	
Other remarks or Concerns:	
Maintainer Information  Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature:  Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025  Phone Number: 651-464-2082 License Number: L216	

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

