## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: @ 6355 2366 34
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.
Date of Maintenance: 8/27/2024 Property ID #:
Property Address: 9718 835 Street N. Grant NW 55082 Street Address City State Zip
Property Owner Name: Rob and Mary Weber
Maintenance Performed
Tanks Pumped:    Emergency
Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit  Tank #1: □ Yes □ No Verification Method Used: □ Gallons Removed: □ Cover Damaged: □ Yes □ No
Tank #2: Des  No Verification Method Used: Gallons Removed: OD  Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No  Tank #3: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Cover Damaged: Yes No
Tank #4: ☐Yes ☐ No Verification Method Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No
Pump Tank:   Yes No Verification Method Used:  Leaking Out:   Yes No Cover Damaged:   Waste Disposal Method:   Treatment plant   Land Apply: Location  Other remarks or Concerns:
Maintainer Information  Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature:  Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025  Phone Number: 651-464-2082 License Number: L216  I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.  Maintenance activities must be reported to the Department within 90 days.

