

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety to				
prior to perform	ning maintenance activitie	s and remain on-	site for the duratio	on of the maintenanc	e activity.
Date of Maintenance:	6/28 /16 Reason fo	or Maintenance: _	ROUTINE		
Property Address: 16	320 ST. MARY	SDR P	operty Owner's Na	me: DAY IDSC	NDMARK
Municipality: <u>ST.MARYS POINT</u> ZIP: <u>55043</u> Property Identification Number: Maintenance Permit No: <u>1886611578</u> Maintainer Name and License No. Meyer Sewer Service/ L915					
Maintenance Permit No	: 1886611578 Ma	intainer Name an	d License No. Meye	Sewer Service/ L915	1
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
X Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers sec 3. Is there evidence o	ove septage: Maintenand curely replaced? Yes If tank leakage from a sept	No ic, holding, pretr	eatment or pump t	ank below the opera	ating depth or
evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
•	Septic/Holding Tank #1	☐ Yes 风No	☐ Yes ☐No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes XNo	☐ Yes PNo	☐ Yes ☐No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed? Tank #1 15 00 gal Tank #2 100 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
					2
6. Location of septage	disposal:	YT			