

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 9/9/2024 Reason	for Maintenance: _	Routine			
Property Address: 10150 Grey Coud Trail S, Cottage Grove, MN Property Owner's Name:				Dave Kelm	
Municipality: ZIP: _550	16 Property Ider	ntification Number:	<u> </u>		
Maintenance Permit No:					
879/375000000 PM2 12 60 03 00 05					
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
☑ Tank(s) Pumped	Liquid Level of 7	Liquid Level of Tank in			
en total inclusion a Markola de Sala Markola de Sala d	Sludge Level in Tank in Scum Level in Tank in				
☐ Sludge and scum measured Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Sci	ım Tar	nks must be pumped	if 25% or greater	
1. Access used to remove septage: \square Maintena	nce Hole 🔀 Other (e	enter authorization co	ode)		
2. Were all covers securely replaced? Yes	∏No N/A				
Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structure	otic, holding, pretr ally unsound main	eatment or pump tenance hole cove	tank below the ope rs? <u>No-couldn't</u> camera	erating depth or confirm precast via	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	Yes No Some answers un	Yes No	Yes No		
Septic/Holding Tank #2		☐ Yes ☐ No	12353		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4 Harrison and the second seco	12				
4. How many gallons of septage were removed Tank #1 500 gal Tank #2 500		t tank a	al Pump Tank	gal	
5. Other information: List any troubleshooting					
37.30 cm - 12.20 m 10.000 - 37.00 m 10.00 m 10		naucteu, tank sait	, 2011201110, 01 001		
Some answers unknown. Pumped through inspec	cuon pipe.	00000			
6. Location of septage disposal: Metro MCES W	A/TD				

Schlomka Services, LLC 17560 Northfield Blvd, Hastings, MN 55033 License# 2989 P: 651-459-3718

Maintenance activities must be reported to the Department within 90 days.