## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 1120 37				
Complete in its entirety to constitute a vamaintenance activities and remain on-sit	alid maintenance p e for the duration	ermit This permit must be	e completed prior to	performing
Date of Maintenance: 9-3-24		Property ID #:	z6268z372	,67
Property Address: 13945 195 Street Address	-th 5TN	mar.'ne	State Zip	
Property Owner Name: Pavid	Shantea	4		
Maintenance Perform	ed			
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Liquid Level Scum Level: Sludge+Scui	Scum Measured: (must be of Tank:inin m/Liquid Level be Pumped if 25% or grea	Sludge Level:x100=	ir
Maintenance Information  Access used to remove septage:  Were all covers securely replaced?  Is the tank designed as a leaky? Ex. So  Tank #1:   Yes No Verification Met  Leaking Out:  Yes No Leaking In	Maintenance Hole Yes□No If No, E eepage pit, cessp hod Used:	xplain: ool drywell leaching pit Gal		
Tank #2:□Yes□ No Verification Met Leaking Out:□Yes□No Leaking In:□	hod Used: Yes □ No Cove	Gal r Damaged:□Yes□No		
Tank #3: □Yes □ No Verification Metl Leaking Out: □Yes □No Leaking In: □ Tank #4: □Yes □ No Verification Metl	Yes ☐ No Cove	Damaged:□Yes□No	lons Removed:	-
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Pump Tank: ☐ Yes ☐ No Verification In: ☐ Leaking Out: ☐ Yes ☐ No Leaking In: ☐	Yes □ No Cover Method Used:	Damaged:□Yes□No Ga	allons Removed:	
Waste Disposal Method: Treatment Other remarks or Concerns:	plant □ Land Ap			
Maintainer Informatio Maintainer Name: Olson's Sewer Service Maintainer Address: 17638 Lyons St. NE Phone Number: 651-464-2082 Lice I hereby certify as a State of Minnesota certified supervised others in the performance of this job. Maintenance activities must be reported.	ce Inc. Forest Lake, MN ense Number: L216 SSTS Maintainer that I	personally conducted the work a	9,	ns, or directly

