

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a va	id maintenance pe	ermit. This permit m	oust be completed	
<u>prior</u> to perfor	ming maintenance activiti	es and remain on	site for the durati	on of the maintenan	ce activity.	
Date of Maintenance:			Rolltine		4	
Property Address: 145	333 & Oakgree.	nCir S. F	roperty Owner's Na	ame: Mike Z	Spross	
Municipality:	ZIP:5500	Property Ider	ntification Number:			
Maintenance Permit No	o: 00,001,000,000 M	aintainer Name ar	d License No. Meye	er Sewer Service/ L91	5	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes Kho	☐ Yes ⊠No	☐ Yes ☑No		
	Septic/Holding Tank #2	☐ Yes XNo	☐ Yes ☑No	☐ Yes I No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed?					
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank					gal	
5. Other information: 154 Tork On With 6. Location of septage	: List any troubleshooting, Original tank Manhok - 3rd	minor repairs co	nducted, tank safe	ty concerns, or other	er concerns.	
o. Location of septage	disposat.					