## **Subsurface Sewage Treatment System Maintenance Permit**

Property/Owner Information Permit #: K71917 37230	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance:	Property ID #:
Property Address: DIGO Finges Soll Due BROSH dawn 55005 Street Address City State Zip  Property Owner Name: DWELL & Barb christofersor	
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scun  Tanks must be Pumped if 25% or greater
Maintenance Information  Access used to remove septager Maintenance Hole Other (enter authorization code)  Were all covers securely replaced? Pos No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit  Tank #1: Pos No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In Yes No Cover Damaged: Yes No Gallons Removed: Gallons Removed: Colors Removed: Callons Removed:	
Leaking Out:   Yes   No Leaking In:   Yes   No Cover Damaged:   Yes   No	
Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location Other remarks or Concerns:	
	est Lake, MN 55025  Number: L216  Vaintainer that I personally conducted the work and made the observations, or directly

