## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Informat	ion Permit #: 57220 g 37275
Complete in its entirety to constitute a valid maintenance activities and remain on-site for t	intenance permit. This permit must be completed prior to performing
Date of Maintenance: 11 SeP 24	Property ID #:
Property Address: 6193 10 wood Street Address	d CT N 55082 City State Zip
Property Owner Name: Garhardt Johnson	
Maintenance Performed	
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scum  Tanks must be Pumped if 25% or greater
Were all covers securely replaced? ☐ Yes ☐ Is the tank designed as a leaky? Ex. Seepa	enance Hole Other (enter authorization code) PIPE ACCESS X :
Leaking Out: ☐ Yes ☑ No Leaking In ☐ Yes ☑	
Leaking Out: ☐ Yes ☑ No Leaking In: ☐ Yes ☑ No Cover Damaged: ☐ Yes ☑ No  Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed:  Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Pump Tank: ☐ Yes ☐ No Verification Method Used: Gallons Removed:   Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location	
Other remarks or Concerns:	
Maintainer Information  Maintainer Name: Smilie's Sewer Service Maintainer Signature:  Maintainer Address: P.O. Box 100 Scandia, MN 55073  Phone Number: 651-433-3935 License Number: L2428	
I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.  Maintenance activities must be reported to the Department within 90 days	

