## **Subsurface Sewage Treatment System Maintenance Permit**

Property/Owner Information Permit #: \5869e 31234	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 99924	
Property Address: 14120 Square Yake Trail Stills to The Bond Street Address City State Zip  Property Owner Name Bill Mann	
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scun  Tanks must be Pumped if 25% or greater
Maintenance Information  Access used to remove septage: Maintenance Hole Other (enter authorization code)  Were all covers securely replaced? Yes No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit  Tank #1: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Cover Damaged: Yes No  Tank #2: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No No Cover Damaged: Yes No  Tank #3: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No No Cover Damaged: Yes No  Tank #4: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No No Cover Damaged: Yes No  Pump Tank: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No No Cover Damaged: Yes No  Waste Disposal Method: Treatment plant Land Apply: Location Other remarks or Concerns:	
I hereby certify as a State of Minnesota certified supervised others in the performance of this job	E Forest Lake, MN 55025 ense Number: L216  SSTS Maintainer that I personally conducted the work and made the observations, or directly

