Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: W1862 37239	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Property Address: 428 Modonals DRW Stylwater Street Address City State Zip	
Property Address: 700 7 Cas round property Address City State Zip Property Owner Name: Argela Faor &	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in _ Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Maintenance Information Access used to remove septage:Maintenance Hole Other (enter authorization code) Were all covers securely replaced	
Tank #3: \Boxedown Yes \Boxedown No Verification Method Used: \Boxedown Gallons Removed: \Boxedown Leaking Out: \Boxedown Yes \Boxedown No Verification Method Used: \Boxedown Gallons Removed: \Boxedown Gallons Removed: \Boxedown Leaking Out: \Boxedown Yes \Boxedown No Verification Method Used: \Boxedown Gallons Removed: \Boxedown Gallons Remov	
Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location	
031 101 2002	

Washington County

Maintenance activities must be reported to the Department within 90 days.