Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit				#:Y0360y3492	Ç.
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 5-16-29					
Property Address: 430 South Street Address	Mo	rin St Baypo	n+	NN 55003 State Zip	
Property Owner Name: Sharon Osmus					
Maintenance Performed					
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection	OR	Liquid Level of Tank:	in	ust be completed if tanks NOT _in Sludge Level: evelx100=%S	in
☐ Repair ☐ Other:		Tanks must be Pumped			
Maintenance Informa Access used to remove septage: Were all covers securely replaced? Is the tank designed as a leaky? Ex. S Tank #1: Yes No Verification Met Leaking Out: Yes No Leaking In: Tank #2: Yes No Verification Met Leaking Out: Yes No Verification Met No Verification Met Leaking Out: Yes No Verification Met	Maint IYes ☐ eepa hod I Yes ☐ hod I IYes ☐ hod I Yes ☐ Weth Yes ☐	enance HoleOther	leachin Yes□ Yes□ Yes□ Yes□	ng pit Gallons Removed: Gallons Removed: No Gallons Removed: No Gallons Removed: No Gallons Removed: No Gallons Removed:	
Other remarks or Concerns: 2 hr		y			
Maintainer Information Maintainer Name: Pinky's Environmenta Maintainer Address: P.O. Box 354 Afton Phone Number: 651-439-4847 I hereby certify as a State of Minnesota certified supervised others in the performance of this job. Maintenance activities must be repo	al Sew , MN ssts w	55001 License Number: L16 laintainer that I personally cond	573 ucted the	1	

