Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Inform	tion Permit #: <u>L5294 +34925</u>	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.		
Date of Maintenance: 5-10-24		Property ID #:
Property Address: 7980 //37 Street Address	n_S+	+ 5 Cottage Grove MN 55016 City State Zip
Property Owner Name: <u>Qaron</u> 2	ly u	viec
Maintenance Perform	ed	
Tanks Pumped: ☐ Emergency	OR	
☐ Home Sale ☐ High-level alarm		Liquid Level of Tank: in Sludge Level: in Scum Level: in
☑ Routine/Maintenance☐ Compliance Inspection		Sludge+Scum/Liquid Levelx100=%Sludge & Scun
☐ Repair ☐ Other:		Tanks must be Pumped if 25% or greater
Maintenance Informa		
		ntenance Hole Other (enter authorization code)
Were all covers securely replaced?		
Is the tank designed as a leaky? Ex. S	age pit, cesspool drywell leaching pit	
Tank #1: ☐ Yes ☑ No Verification Met	Used: 1/isual Gallons Removed: 1250	
Leaking Out: ☐ Yes ☐ No Leaking In ☐	☑ No Cover Damaged: ☐ Yes ☑ No	
Tank #2:□Yes□ No Verification Met	Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐		
	Used: Gailons Removed:	
	□ No Cover Damaged:□Yes□No	
Tank #4: ☐Yes ☐ No Verification Met		
Leaking Out:□Yes□No Leaking In:□		
Pump Tank: ☐ Yes ☐ No Verification		
Leaking Out:□Yes□No Leaking In:□		
Waste Disposal Method: ☐ reatmen		
Other remarks or Concerns: _ Nov		
Maintainer Information	าท	
Maintainer Name: Pinky's Environment		Maintainer Signature At Of M
Maintainer Address: P.O. Box 354 Aftor	——————————————————————————————————————	
Phone Number: 651-439-4847	License Number: L1673	
I hereby certify as a State of Minnesota certified supervised others in the performance of this job	Maintainer that I personally conducted the work and made the observations, or directly	
Maintenance activities must be repo	to the Department within 90 days.	

Washington County