## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Inform	nation Permit #: 1493 k 37243
Complete in its entirety to constitute a val maintenance activities and remain on-site	id maintenance permit. This permit must be completed prior to performing for the duration of the maintenance activity.
Date of Maintenance: 9~18~24	Property ID #:
Property Address: 6991 132 ~ Street Address	City State Zip
Property Owner Name: Randal Barnes	
Maintenance Performe	ed
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:ir  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scur  Tanks must be Pumped if 25% or greater
Maintenance Informat	ion
Access used to remove septage:M	aintenance Hole Other (enter authorization code)
Were all covers securely replaced	
Is the tank designed as a leaky? Ex. Se	epage pit, cesspool drywell leaching pit
lank #1: ☐Yes No Verification Meth	od Used: Gallons Removed:
Leaking Out: ☐ Yes ⚠ O Leaking In ☐ Ye	
	od Used: Gallons Removed:
Leaking Out: Yes No Leaking In:	
	od Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ \	
Tank #4: Lives Live Verification Meth	od Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Y	
Pump Tank: Yes No Verification M	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Y	
	plant ☐ Land Apply: Location
Other remarks or Concerns:	
Maintainer Information  Maintainer Name: Olson's Sewer Service Inc.  Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025  Phone Number: 651-464-2082  License Number: L216	

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

