Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 0100 108 x 37248	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Property Address: 14/95 In 34 AUR W Hayson Property Owner Name: Chad Hanson	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scur Tanks must be Pumped if 25% or greater
Maintenance Information	
Access used to remove septage: Maintenance Hole Other (enter authorization code)	
Were all covers securely replaced YstYes□No If No, Explain:	
Is the tank designed as a leaky? Ex. See	page pit, cesspool drywell leaching pit
Tank #1: Lives Without Verification Method	Used: Gallons Removed:_/こうこ
Leaking Out: ☐ Yes ☐ No Leaking In ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #2:□ Yes No Verification Method Used: Gallons Removed: Gallons Removed: Cover Damaged: □ Yes No Cover	
Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Fallons Removed:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Pump Tank: Yes No Verification Method Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Waste Disposal Method: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Waste Disposal Method: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
The state of the s	
Other remarks or Concerns:	
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216	

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

