Subsurface Sewage Treatment System Maintenance Permit

Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.
Date of Maintenance: 6-27-24 Property ID #:
Property Address: 8610 Kmbro Cn No Stillector Thy 55082 Street Address City State Zip Property Owner Name: Will Bruen
Maintenance Performed
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other: Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No If No, Explain: Monthole is half under Petro Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: Yes No Verification Method Used:
Leaking Out: Yes ☐ No Leaking In ☐ Yes ☐ No Cover Damaged: Yes ☐ No Tank #2: ☐ Yes ☐ No Verification Method Used: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No
Tank #3: ☐ Yes ☐ No Verification Method Used: ☐ Gallons Removed: ☐ ☐ Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Tank #4: ☐ Yes ☐ No Verification Method Used: ☐ Gallons Removed: ☐ Gallons Removed: ☐ Gallons Removed: ☐ Head of the control o
Leaking Out: Yes No Cover Damaged: Yes No Pump Tank: Yes No No Verification Method Used: Gallons Removed:
Maintainer Information Maintainer Name: Pinky's Sewer Service Inc. Maintainer Signature: Maintainer Address: P.O. Box 354 Afton, MN 55001 Phone Number: 651-439-4847 License Number: L4251 I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintenance activities must be reported to the Department within 90 days.

Washington County