## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Inform	nation Permit #: 0 4240 11 37752
Complete in its entirety to constitute a val maintenance activities and remain on-site	lid maintenance permit. This permit must be completed prior to performing for the duration of the maintenance activity.
Date of Maintenance: 9-25-24	Property ID #:
Property Address: 21480 Oren Ave N Scandia State Zip  Property Owner Name: Todd Peterson	
Maintenance Performe  Tanks Pumped: □ Emergency □ Home Sale □ High-level alarm Routine/Maintenance □ Compliance Inspection □ Repair	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scur  Tanks must be Pumped if 25% or greater
Other:  Maintenance Informat  Access used to remove septage:  Mara all a septage	faintenance Hole Other (enter authorization code)
Were all covers securely replaced	Yes□No If No, Explain:epage pit, cesspool drywell leaching pit
Tank #1:□Yes ANO Verification Meth Leaking Out:□Yes ANO Leaking In□Yo Tank #2:□Yes YNO Verification Meth	nod Used: Gallons Removed:/150
Tank #3:□Yes □ No Verification Meth Leaking Out:□Yes□No Leaking In:□Y	rod Used: Gallons Removed: SSCO Yes □ No Cover Damaged:□Yes□No
Tank #4: ☐ Yes ☐ No Verification Meth	
Pump Tank: ☐ Yes ☐ No Verification M Leaking Out: ☐ Yes ☐ No Leaking In: ☐ N	Yes ☐ No Cover Damaged: ☐ Yes ☐ No  Method Used: Gallons Removed:  Yes ☐ No Cover Damaged: ☐ Yes ☐ No  plant ☐ Land Apply: Location
Maintainer Information Maintainer Name: Olson's Sewer Service Maintainer Address: 17638 Lyons St. NE Phone Number: 651-464-2082 Lice	e Inc. Maintainer Signature:

supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

