Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information		Permit #: NO281; 35565
Complete in its entirety to constitute a valid n maintenance activities and remain on-site for	aintenance normit This no	armait marret les L. L. L
Date of Maintenance: 6-21-24	Property ID	#:
Property Address: 9180 Stone b	ridge Tr N . City	Still MN 55087
Property Owner Name: Dan Schult	2	
Maintenance Performed		
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm		ed: (must be completed if tanks NOT pumped)in Sludge Level:in
☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair		iquid Levelx100=%Sludge & Scun
☐ Other: Maintenance Information Access used to remove septage: Maint Were all covers securely replaced? ☐ Yes [enance HoleOther (
Is the tank designed as a leaky? Ex. Seepa Tank #1:□Yes ☑ No Verification Method Leaking Out:□Yes☑No Leaking In□Yes☑	Used: Visual	Gallons Removed: 1750
Tank #2:□Yes□ No Verification Method Used:		Gallons Removed:
Tank #3: ☐ Yes ☐ No Verification Method Used:		Gallons Removed:
Tank #4: ☐ Yes ☐ No Verification Method Used:		Gallons Removed:
Pump Tank: ☐ Yes ☐ No Verification Meth Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Waste Disposal Method: ☐ Treatment plar Other remarks or Concerns: ☐ ☐ One	od Used: □ No Cover Damaged:□ it □ Land Apply: Locatior	Gallons Removed:]Yes□No
Maintainer Information Maintainer Name: Pinky's Sewer Service Inc. Maintainer Address: P.O. Box 354 Afton, MN Phone Number: 651-439-4847	Maintainer Signature 55001 License Number: L4	
I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintenance activities must be reported to the Department within 90 days.		

Washington County