Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: p3338 z34830	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 6-13-24	Property ID #:
	clye Arc Ct No Stillwater MM 5508Z City State Zip
Property Owner Name: Bruce Mayhause	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
	enance Hole Other (enter authorization code) over top of Many Cles ge pit, cesspool drywell leaching pit
Tank #1:□Yes ☑ No Verification Method Leaking Out:□Yes ☑ No Leaking In □Yes ☐	Used: Gallons Removed: Sociation
Tank #2:□Yes ☐ No Verification Method Leaking Out:□Yes ☐ No Leaking In: □ Yes	Used: Gallons Removed: Gallons Removed:
	Used: Gallons Removed:
Tank #4: ☐ Yes ☐ No Verification Method Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	
Pump Tank: ☐ Yes ☐ No Verification Meth Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Waste Disposal Method: ☐ Treatment plan Other remarks or Concerns:	
Maintainer Information Maintainer Name: Pinky's Environmental Sev Maintainer Address: P.O. Box 354 Afton, MN Phone Number: 651-439-4847 I hereby certify as a State of Minnesota certified SSTS I supervised others in the performance of this job.	

Washington County

Maintenance activities must be reported to the Department within 90 days.