## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Infor	ation Bermit # 195	33034901
Complete in its entirety to constitute a v	maintenance permit. This permit must be complor the duration of the maintenance activity.	eted prior to performing
	Property ID #:	
Property Address: 3873 22 Street Address	el St Ct No Stilluc City State	nter WM 5508
Maintenance Perform		
Tanks Pumped: ☐ Emergency ☐ Home Sale	R Sludge and Scum Measured: (must be completed) Liquid Level of Tank:in Sl	• •
☐ High-level alarm	Scum Level:in Sludge+Scum/Liquid Level;	x100=%Sludge & Scum
☐ Repair ☐ Other:	Tanks must be Pumped if 25% or greater	
Were all covers securely replaced? ☐ Is the tank designed as a leaky? Ex. S ☐ Tank #1: ☐ Yes ☐ No Verification Met Leaking Out: ☐ Yes ☐ No Verification Met Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Tank #3: ☐ Yes ☐ No Verification Met	other (enter authorization of No, Explain:  Dage pit, cesspool drywell leaching pit  Used:  ☐ Used: ☐ Cover Damaged:☐ Yes☐ No ☐ Used: ☐ Gallons Re	emoved:/500
Tank #4:□Yes □ No Verification Method Used:		moved:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Pump Tank: ☐ Yes ☐ No Verification In: ☐ Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Waste Disposal Method: ☐ Treatment Other remarks or Concerns:	thod Used:Gallons R s□No Cover Damaged:□Yes□No ant □ Land Apply: Location	emoved:
Maintainer Information  Maintainer Name: Pinky's Environmental Sewer Service Inc. Maintainer Sign  Maintainer Address: P.O. Box 354 Afton, MN 55001  Phone Number: 651-439-4847 License Number: L1673		
I hereby certify as a State of Minnesota certified supervised others in the performance of this job.  Maintenance activities must be repo	Maintainer that I personally conducted the work and made	the observations, or directly

Washington **County**