Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #		ermit#:052230,25149
	alid maintenance permit. This pern	nit must be completed prior to performing
Date of Maintenance: 5-8-24	Property ID #:	
Property Address: 7660 64th Street Address	St N Pine Springe	State Zip
Property Owner Name: <u>Linda</u> N	1c Gratk	2.0
Maintenance Perform	ed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Liquid Level of Tank:	uid Levelx100=%Sludge & Scum
Maintenance Informa Access used to remove septage:i Were all covers securely replaced? Is the tank designed as a leaky? Ex. S	Maintenance Hole <u>1∕</u> Other (er 1Yes□No If No, Explain:	
Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching Tank #1: ☐ Yes ☑ No Verification Method Used:		Gallons Removed: 1250
Tank #2:☐ Yes ☐ No Verification Method Used: Leaking Out:☐ Yes☐ No Leaking In:☐ Yes☐ No Cover Damaged:☐ Yes☐		Gallons Removed:
Tank #3:□Yes □ No Verification Method Used: Leaking Out:□Yes□No Leaking In:□Yes□No Cover Damaged:□Yes□		Gallons Removed: Yes□No
Tank #4: ☐ Yes ☐ No Verification Method Used:		Gallons Removed: Yes□No
Pump Tank: ☐ Yes ☐ No Verification Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Waste Disposal Method: ☐ Treatment Other remarks or Concerns:	Yes□No Cover Damaged:□\	
Maintainer Information Maintainer Name: Pinky's Environmenta Maintainer Address: P.O. Box 354 Afton Phone Number: 651-439-4847 I hereby certify as a State of Minnesota certified supervised others in the performance of this job. Maintenance activities must be repo	al Sewer Service Inc. Maintaine , MN 55001 License Number: L1673 SSTS Maintainer that I personally conduct	ted the work and made the observations, or directly

Washington County