Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: \16366x354122	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing	
Date of Maintenance: 6-7-24	Property ID#: Property ID#: City State Zip Mary Juhnson
Property Address: 4980 Gasp Street Address	er ave Lake Elmo MN 55047
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in
☐ High-level alarm ☐ Boutine/Maintenance	Scum Level:in
☐ Compliance Inspection ☐ Repair	Sludge+Scum/Liquid Levelx100=%Sludge & Scum
☐ Other:	Tanks must be Pumped if 25% or greater
Maintenance Information Access used to remove septage: Maintenance HoleOther (enter authorization code) Were all covers securely replaced?Yes No If No, Explain:	
Is the tank designed as a leaky? Ex. Seena	ge nit resspool drawell leaching with
Tank #1: ☐ Yes ☐ No Verification Method I	Jsed: Visual Gallons Romandy 150
Leaking Out. Tespho Leaking in Tyes	No Cover Damaged:□Yes□No
Leaking Out: ☐ Yes ☐ No Verification Method L	Jsed: Gallons Removed:
Tank #3: ☐ Yes ☐ No Verification Method I	Isod:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	Jsed: Gallons Removed:
Tank #4:□Yes □ No Verification Method L	Jsed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	No Cover Damaged:□Yes□No
Pump Tank: ☐ Yes ☐ No Verification Metho	od Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	No Cover Damaged:□Yes□No
Waste Disposal Method: Treatment plan	t □ Land Apply: Location www TP
Other remarks or Concerns: Mone	
Maintainer Information Maintainer Name: Pinky's Sewer Service Inc. Maintainer Signature. Maintainer Signature.	
Maintainer Address: P.O. Box 354 Afton, MN 55001	
	License Number: L4251 aintainer that I personally conducted the work and made the observations, or directly the Department within 90 days

Washington County