Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 2 9856434891	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing naintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 6-4-24	Property ID #:
Property Address: 15216 After Street Address	Blue So Aften MM 5508) City State Zip
Property Owner Name: Alison Green	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum
☐ Repair ☐ Other:	Tanks must be Pumped if 25% or greater
Were all covers securely replaced? ☐ Yes ☐ Is the tank designed as a leaky? Ex. Seepa	ge pit, cesspool drywell leaching pit Used: Gallons Removed: TNo Cover Damaged:Yes No Used: Gallons Removed: No Cover Damaged:Yes No
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	
Tank #4: ☐ Yes ☐ No Verification Method Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	
Pump Tank: Yes No Verification Methods No Use In: Yes Waste Disposal Methods Treatment plan	od Used: Gallons Removed: □ No Cover Damaged:□Yes□No
Other remarks or Concerns:	
Maintainer Information Maintainer Name: Pinky's Environmental Sewer Service Inc. Maintainer Address: P.O. Box 354 Afton, MN 55001 Phone Number: 651-439-4847 License Number: L1673 I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintenance activities must be reported to the Department within 90 days.	

Washington County