Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: h2852\36341	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performaintenance activities and remain on-site for the duration of the maintenance activity.	ming
Date of Maintenance: 7-23-24 Property ID #:	
Property Address: 1875 Quells Arc So (City State Zin State Zin	13
Property Owner Name: Susan Lissick	
Maintenance Performed	
Tanks Pumped: Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection OR Sludge and Scum Measured: (must be completed if tanks NOT put Liquid Level of Tank:	in
☐ Repair ☐ Other: Tanks must be Pumped if 25% or greater	
Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: Yes No Verification Method Used: Gallons Removed:	
Leaking Out: ✓ Yes No Cover Damaged: ✓ Yes No Tank #2: ✓ Yes No Visual Gallons Removed: ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓	
Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Pump Tank: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Pump Tank: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Waste Disposal Method: Treatment plant ☐ Land Apply: Location Other remarks or Concerns: old System, system filly	
Maintainer Information Maintainer Name: Pinky's Sewer Service Inc. Maintainer Signature: Maintainer Address: P.O. Box 354 Afton, MN 55001 Phone Number: 651-439-4847 License Number: 14251	

Washington County