## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Informat	ion Permit #: Y 6867 e 36087
Complete in its entirety to constitute a valid ma maintenance activities and remain on-site for the	aintenance permit. This permit must be completed prior to performing
	Property ID #:
	n Ln No Cake Elmo MM 5504 City State Zip
Property Owner Name: Many F	elland
Maintenance Performed	
Tanks Pumped:  □ Emergency □ Home Sale □ High-level alarm □ Routine/Maintenance □ Compliance Inspection	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scum
☐ Repair ☐ Other:	Tanks must be Pumped if 25% or greater
Were all covers securely replaced?□Yes□ Is the tank designed as a leaky? Ex. Seepag	ge pit, cesspool drywell leaching pit  Jsed: Gallons Removed: 1750
	Jsed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Tank #3: ☐ Yes ☐ No Verification Method L Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	□ No Cover Damaged: □ Yes □ No  Used: □ Gallons Removed: □ Gallons
Tank #4: ☐Yes ☐ No Verification Method L	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
Pump Tank: ☐ Yes ☐ No Verification Method Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Waste Disposal Method  Treatment plan Other remarks or Concerns:	No Cover Damaged: ☐ Yes ☐ No
Maintainer Information Maintainer Name: Pinky's Sewer Service Inc. Maintainer Address: P.O. Box 354 Afton, MN Phone Number: 651-439-4847	License Number: L4251  aintainer that I personally conducted the work and made the observations, or directly

Washington County