Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: <u>V3592n35846</u>	
Complete in its entirety to constitute a valid r maintenance activities and remain on-site for	maintenance permit. This permit must be completed prior to performing r the duration of the maintenance activity.
	Property ID #:
Property Address: 4416 Holm 0 Street Address	City State Zip
Property Owner Name: 8 Jim Frid	
Maintenance Performed	
Tanks Pumped: Emergency Home Sale High-level alarm Routine/Maintenance Compliance Inspection Repair Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Maintenance Information	n
Were all covers securely replaced? ☐ Yes Is the tank designed as a leaky? Ex. Seep	d Used: Visua Gallons Removed: 1500
Tank #2:□ Yes □ No Verification Method	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Ye Tank #3: ☐ Yes ☐ No Verification Method	es □ No Cover Damaged: □ Yes □ No d Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Ye	s □ No Cover Damaged: □ Yes □ No
Tank #4: ☐ Yes ☐ No Verification Method Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Ye	
Pump Tank: ☐ Yes ☐ No Verification Me Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Ye Waste Disposal Method: ☐ Treatment pl Other remarks or Concerns:	es □ No Cover Damaged: □ Yes □ No lant □ Land Apply: Location www.
Maintainer Information Maintainer Name: Pinky's Sewer Service In Maintainer Address: P.O. Box 354 Afton, N Phone Number: 651-439-4847 I hereby certify as a State of Minnesota certified SST: supervised others in the performance of this job.	nc. Maintainer Signature



Maintenance activities must be reported to the Department within 90 days.