Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information

Property/Owner Inform	nation Perm	it #: <u>N3426v36495</u>
Complete in its entirety to constitute a va maintenance activities and remain on-site	alid maintenance permit. This permit reference for the duration of the maintenance	must be completed prior to performing
Date of Maintenance: 8-20-2		
Property Address: 3911 OSO Street Address	cool Are No S-	tillucater MM 5508 State Zip
Property Owner Name: William	m Melson	
Maintenance Perform	ed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Liquid Level of Tank:in	Levelx100=%Sludge & Scur
□ Other:		oi greater
Access used to remove septage:N Were all covers securely replaced? □ Is the tank designed as a leaky? Ex. So Tank #1: □Yes □ No Verification Met	Yes□No If No, Explain:eepage pit, cesspool drywell leach hod Used:	ing pit Gallons Removed: (250)
Leaking Out: ☐ Yes ☐ No Verification Met		
Leaking Out: ☐ Yes ☐ No Leaking In: ☐		
Tank #3: ☐ Yes ☐ No Verification Method Used:		Gallons Removed:
Leaking Out: ☐Yes ☐No Leaking In: ☐		
Tank #4: ☐ Yes ☐ No Verification Metl Leaking Out: ☐ Yes ☐ No Leaking In: ☐		Gallons Removed:
Pump Tank: Yes No Verification No Leaking Out: Yes No Leaking In: Waste Disposal Method: Treatment Other remarks or Concerns:	Method Used: <u>Usual</u> Yes ☑No Cover Damaged: Yes plant □ Land Apply: Location <u>u</u>	Gallons Removed:
Maintainer Informatio	n	112
Maintainer Name: Pinky's Sewer Service Maintainer Address: P.O. Box 354 Aftor Phone Number: 651-439-4847	n, MN 55001	
I hereby certify as a State of Minnesota certified supervised others in the performance of this job. Maintenance activities must be reported.		he work and made the observations, or directly

Washington County