Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 69163 × 36511	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: OE/Q DOU Property ID #:	
Property Address: 12695 Manuay Tri No Stillutto MM 55087 Street Address City State Zip	_
Property Owner Name: Robert Mchar	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other: Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level: Scum Level:in Sludge+Scum/in Sludge+Scum/in Sludge Level:in Sludge+Scum/in Sludge Level:in Sludge Level:	
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? ✓ Yes□No If No, Explain:	
Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1:□Yesd No Verification Method Used: 1560 Gallons Removed: 1560	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #2:□Yes □ No Verification Method Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Pump Tank: Yes No Verification Method Used: Gallons Removed: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No	
Waste Disposal Method: Treatment plant Land Apply: Location Other remarks or Concerns: home owner Concident is digits up manhole, used Pipe	
Maintainer Information Maintainer Name: Pinky's Sewer Service Inc. Maintainer Signature: Maintainer Address: P.O. Box 354 Afton, MN 55001 Phone Number: 651-439-4847 License Number: L4251	

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

