Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Inform	ation Permit #: <u>17074 w 37562</u>
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 10/7/24	Property ID #:
Property Address: <u>9775</u> 23544 54 Street Address	City State Zip
Property Owner Name: Sohn F. Olson	
Maintenance Performed	d
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scur Tanks must be Pumped if 25% or greater
	intenance Hole Other (enter authorization code) es□No If No, Explain:
Tank #1: ☐Yes No Verification Metho Leaking Out: ☐ Yes No Leaking In ☐ Yes	od Used: Visua/ Gallons Removed: 1100
Tank #2:□Yes Mo Verification Metho Leaking Out:□Yes Mo Leaking In: □Yes	od Used: Visual Gallons Removed: 1600 Gallo
Tank #3:□Yes □ No Verification Metho Leaking Out:□Yes□No Leaking In:□Ye	od Used: Gallons Removed: es □ No Cover Damaged:□Yes□No
Tank #4: ☐ Yes ☐ No Verification Method Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	es □ No Cover Damaged:□Yes□No
Pump Tank: ☐ Yes ☐ No Verification Me Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Ye Waste Disposal Method: ☐ Treatment pl Other remarks or Concerns:	
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216	

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

