Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information	Permit #: 16541 V36394
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 09/13/2e24 Property ID #:	
Property Address: 9920 Heron Ave N Street Address	White Bear Lake MN 55110 City State 7in
Property Owner Name: Molly Donovan	
Maintenance Performed	
☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Banair	cum Measured: (must be completed if tanks NOT pumped) of Tank:in
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced Yes \(\) No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: \(\) Yes \(\) No Verification Method Used:/ \(\) \(
Leaking Out: Yes No Leaking In Yes No Cover D	amaged:□Yes☑No Gallons Removed:
Tank #2: \\\ Voc \\\\ No \\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Gallons Removed:
Tank #4: ☐ Yes ☐ No Verification Method Used:	Gallons Removed: Damaged:□ Yes□ No Gallons Removed:
Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Waste Disposal Method: Treatment plant Land Apply: Location Other remarks or Concerns: Note owher Did Not want hanhale Cover dua up.	
Maintainer Information Maintainer Name: Pinky's Sewer Service Inc. Maintainer Maintainer Address: P.O. Box 354 Afton, MN 55001	Number: L4251 rsonally conducted the work and made the observations, or directly

Washington County