## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 02087p37505			505	
Complete in its entirety to constitute a valid maintenance activities and remain on-site f	I maintenance permit. or the duration of the	This permit must be	completed prior to	
Date of Maintenance: 10/8/24	Prop	erty ID #:		
Property Address: 21985 Parnish 1 Street Address		Canding lity	MW 5507 State Zip	3
Property Owner Name: Kari Riermann				
Maintenance Performed				
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Liquid Level of Ta Scum Level: Sludge+Scum/	Measured: (must be nk:inininLiquid Level amped if 25% or grea	Sludge Level:x100=	in
Maintenance Informati	on			
Access used to remove septage: Ma	es□No If No, Explain	n:		
Is the tank designed as a leaky? Ex. See				A (7)
Tank #1: ☐ Yes → No Verification Method Used: Gallons Removed: Gallons Removed: Cover Damaged: ☐ Yes → No				
Tank #2:□ Yes ☑ No Verification Metho Leaking Out:□ Yes ☑ No Leaking In: □ Yes	d Used: Visual	Gal	lons Removed: 10	100
Tank #3: ☐ Yes ☐ No Verification Metho			lons Removed:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Ye	es □ No Cover Dan	naged:□Yes□No		
Tank #4: ☐Yes ☐ No Verification Metho	d Used:	Gal	lons Removed:	
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No				
Pump Tank: ☐ Yes ☐ No Verification Method Used: Gallons Removed:				
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No				
Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location				
Other remarks or Concerns:				
Maintainer Information Maintainer Name: Olson's Sewer Service Maintainer Address: 17638 Lyons St. NE F Phone Number: 651-464-2082 Licen	Inc. orest Lake, MN 55025	Maintainer Signatur	e: W	A

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly

Maintenance activities must be reported to the Department within 90 days.

supervised others in the performance of this job.