Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information

Property/Owner Information Permit #: 16596037568
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.
Date of Maintenance: Property ID #:
Property Address: 8265 Scondig trail Reest Lake MW 55825 Street Address City State Zip
Property Owner Name: ASAD & Kristey Sheriff
Maintenance Performed
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other: Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Sludge Level:in Tanks must be Pumped if 25% or greater
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced wes No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1
Tank #3:□Yes □ No Verification Method Used: Gallons Removed: Leaking Out:□Yes□No Leaking In: □ Yes □ No Cover Damaged:□Yes□No
Tank #4: □Yes □ No Verification Method Used: Gallons Removed: Leaking Out: □Yes □ No Leaking In: □Yes □ No Cover Damaged: □Yes □ No Pump Tank: □Yes □ No Verification Method Used: Gallons Removed: Leaking Out: □Yes □ No Leaking In: □Yes □ No Cover Damaged: □Yes □ No
Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: LocationOther remarks or Concerns:
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature:

