Subsurface Sewage Treatment System Maintenance Permit

Complete in its entirety to constitute a vali maintenance activities and remain on-site	d maintenance permit. T for the duration of the m	his permit must be of aintenance activity.	completed prior to	performing
Date of Maintenance: 10-14-24	Proper	ty ID #:		
Property Address: 20 4/1 3 2 4 2 Street Address Property Owner Name: 4 4 6 6	1 Alex F.	<u>ζ</u> -	State Zip	
Property Owner Name:	Triden			
Maintenance Performe	d			
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Liquid Level of Tank Scum Level: Sludge+Scum/	leasured: (must be o	Sludge Level: _ x100=	in
Maintenance Informat Access used to remove septage: Mere all covers securely replaced? Is the tank designed as a leaky? Ex. Se Tank #1: Yes No Verification Meth Leaking Out: Yes No Leaking In	aintenance Hole (es □ No If No, Explain: epage pit, cesspool dr od Used:	/well leaching pit Gall		
Tank #2:□Yes ♠No Verification Meth Leaking Out:□Yes ♠No Leaking In:□'	od Used: ⁄es ⁄⊠t No Cover Dama	Gallaged:□Yes⊠No		
Tank #3: ☐ Yes ☐ No Verification Meth Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Verification Meth	/es □ No Cover Dama od Used:	aged:□Yes□No Gall		
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Verification Mover Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Verification Move In	lethod Used: /es □ No Cover Dama	Ga aged:□Yes□No	allons Removed:	
Maintainer Informatio Maintainer Name: Olson's Sewer Service Maintainer Address: 17638 Lyons St. NE Phone Number: 651-464-2082 Lice	e Inc.	Maintainer Signature	e: Alfr	

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly

Maintenance activities must be reported to the Department within 90 days.

Washington County

Permit #: 04969x37580

supervised others in the performance of this job.

Property/Owner Information