Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Inforn	nation Permit #: 6500 6933-163-782
Complete in its entirety to constitute a valuation maintenance activities and remain on-site	lid maintenance permit. This permit must be completed prior to performing for the duration of the maintenance activity.
Date of Maintenance: 10-14-24	~
Property Address: Street Address	All follow Leke MW 55005 City State Zip
Property Owner Name:	
Maintenance Performe	ed
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Were all covers securely replaced? ☐ Is the tank designed as a leaky? Ex. Se Tank #1 ☐ Yes ☐ No Verification Meth	Alaintenance Hole Other (enter authorization code) Yes No If No, Explain: eepage pit, cesspool drywell leaching pit nod Used: Gallons Removed: Yes No Cover Damaged: Yes
Leaking Out: ☐ Yes ☐ No Leaking In: ☐	rod Used: Gallons Removed: LDD Yes □ No Cover Damaged: □ Yes □ No Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Tank #4: ☐ Yes ☐ No Verification Meth	Yes □ No Cover Damaged:□Yes□No
Pump Tank: ☑ Ses ☐ No Verification N Leaking Out: ☐ Yes ☐ No Leaking In: ☐	Method Used: Gallons Removed: Yes □ No Cover Damaged:□Yes□No plant □ Land Apply: Location
Maintainer Informatio Maintainer Name: Olson's Sewer Service Maintainer Address: 17638 Lyons St. NE Phone Number: 651-464-2082 Lice I hereby certify as a State of Minnesota certified Supervised others in the performance of this job.	n ce Inc. Maintainer Signature:

