## **Subsurface Sewage Treatment System Maintenance Permit**

Property/Owner Information

Property/Owner Inform	nation	Permit #	W14751	137576	
Complete in its entirety to constitute a va maintenance activities and remain on-site	lid maintenance for the duration	permit. This permit must n of the maintenance ac	st be completed tivity.	prior to perform	ing
Date of Maintenance: 160672024		Property ID #:			
Property Address: 11605 1164% 54 Street Address	N	Sillwater	MN State Z	96082	
Property Owner Name: William + T	heresa Gir	somen			
Maintenance Perform	ed				
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☑ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Liquid Lev Scum Leve Sludge+Sc	d Scum Measured: (musel of Tank:in  um/Liquid Levest be Pumped if 25% or	in Sludge	e Level:	in
Maintenance Informat	tion				
Were all covers securely replaced? Is the tank designed as a leaky? Ex. So Tank #1: I Yes No Verification Met Leaking Out:	Yes□No If No, eepage pit, cess hod Used:	Explain:spool drywell leaching  or Damaged:YesN  or Damaged:YesN  or Damaged:YesN  or Damaged:YesN  or Damaged:YesN	Gallons Removed Gallons Removed No Gallons Removed Gallons Removed Gallons Removed Gallons Removed	ved:ved:ved:	
Other remarks or Concerns:					_
Maintainer Information Maintainer Name: Olson's Sewer Servit Maintainer Address: 17638 Lyons St. NE Phone Number: 651-464-2082 Lice I hereby certify as a State of Minnesota certified supervised others in the performance of this iob.	ce Inc. E Forest Lake, MI ense Number: L2	N 55025 16	work and made the	,	ectly



Maintenance activities must be reported to the Department within 90 days.