Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information	Permit #: C4690K37574
Complete in its entirety to constitute a valid maintenance activities and remain on-site for	maintenance permit. This permit must be completed prior to performing the duration of the maintenance activity.
Date of Maintenance: 10/15/24	Property ID #:
Property Address: 10158 122 N	O ST HUGO MN 55038 City State Zip
Property Owner Name: Chenty Classical Academy	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scur Tanks must be Pumped if 25% or greater
Maintenance Information	n n
Were all covers securely replaced? Ye Is the tank designed as a leaky? Ex. See Tank #1: ☐ Yes ☑ No Verification Method Leaking Out: ☐ Yes ☑ No Leaking In ☐ Yes Tank #2: ☐ Yes ☑ No Leaking In: ☐ Yes	Gallons Removed: 2750 Cover Damaged: Yes No Gallons Removed: 2750 Gallons Removed: 2750 Gallons Removed: 2750 Gallons Removed: 400 Gallons Removed: 4000
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Ye	
Waste Disposal Method:	



Maintenance activities must be reported to the Department within 90 days.