Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 23358137954		
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.		
Date of Maintenance: <u>IDD 10/18/24</u>		Property ID #:
Property Address: 22350 Kirk Street Address	CT	Scandia MN 55073 City State Zip
Property Owner Name:		
Maintenance Perform	ed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	OR	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank: in Sludge Level: ir Scum Level: in Sludge+Scum/ Liquid Level x100= %Sludge & Scur Tanks must be Pumped if 25% or greater
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced responsible to the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Tank #2: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Tank #3: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Tank #4: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Pump Tank: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Verification Method Used: Gallons Removed:		
Leaking Out: ☐ Yes INO Leaking In: ☐ Yes INO Cover Damaged: ☐ Yes INO Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location Other remarks or Concerns:		
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature: Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216 I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintenance activities must be reported to the Department within 90 days.		

