Subsurface Sewage Treatment System Maintenance Permit

Froperty/Owner informa-	tion Permit #: M	3607 x 3 1629
Complete in its entirety to constitute a valid m maintenance activities and remain on-site for	naintenance permit. This permit must be	completed prior to performing
Date of Maintenance: // OCT 29	Property ID #:	
Property Address: 1021 Quan Street Address	t AN N	55047
Street Address	City	State Zip
Property Owner Name: JUhn Peat	VOSS	
Maintenance Performed	VI VI SIS	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm	Liquid Level of Tank:in	
⊠ Routine/Maintenance	Scum Level:in	
☐ Compliance Inspection	Sludge+Scum/Liquid Level	x100=%Sludge & Scu
☐ Repair ☐ Other:	Tanks must be Pumped if 25% or grea	ter
Maintenance Informatio	n	Minimum of Marketine in the Control of the Control
Access used to remove septage: Main		ization code) PIRe
Were all covers securely replaced?⊠Yes[□No If No, Explain:	
Is the tank designed as a leaky? Ex. Seepa		
Tank #1:□Yes ☑No Verification Method		lons Removed: 500
Leaking Out: ☐ Yes∰No Leaking In:☐ Yes ₩	∃ No Cover Damaged: Yes No	
Tank #2:□Yes□ No Verification Method	Used: Gal	lons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes		
Tank #3:□Yes □ No Verification Method	Used: Gal	lons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes		
Tank #4: ☐ Yes ☐ No Verification Method		lons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes		
Pump Tank: ☐ Yes ☐ No Verification Meth		allons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes		
Waste Disposal Method: ☐ Treatment pla	nt 🔁 Land Apply: Location	
Other remarks or Concerns:		
Maintainer Information Maintainer Name: Smilie's Sewer Service Maintainer Address: P.O. Box 100 Scandia Phone Number: 651-433-3935 License	Maintainer Signatur a, MN 55073 Number: _{L2428}	re: 15
I hereby certify as a State of Minnesota certified SSTS I supervised others in the performance of this job. Maintenance activities must be reported		and made the observations, or directly

