## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Inform	mation Permit #: <u>m81018 a 37587</u>
Complete in its entirety to constitute a variation and remain on-sit	alid maintenance permit. This permit must be completed prior to performing e for the duration of the maintenance activity.
Date of Maintenance: 10-17-20	Property ID #:
Property Address: 10760 /8 Street Address	City State Zip
Property Address: 10460 180th STN F.L.  Street Address City State Zip  Property Owner Name: Betsey Perreault	
Maintenance Perform	ed
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scun  Tanks must be Pumped if 25% or greater
Were all covers securely replaced?	Vaintenance Hole Other (enter authorization code)  Yes□No If No, Explain:
Is the tank designed as a leaky? Ex. S	eepage pit, cesspool drywell leaching pit
Leaking Out:☐Yes⊠No Leaking In☐\	hod Used: Gallons Removed: Completed: Gallons Removed: Completed: Gallons Removed: Completed:
Leaking Out: Yes And Leaking In:	Yes No Cover Damaged: ☐ Yes No
Tank #3:□Yes □ No Verification Met Leaking Out:□Yes□No Leaking In: □	hod Used: Gallons Removed: Yes □ No Cover Damaged:□Yes□No
Tank #4: ☐Yes ☐ No Verification Metl	
Pump Tank: ☐ Yes ☐ No Verification N Leaking Out: ☐ Yes ☐ No Leaking In: ☐	Yes □ No Cover Damaged:□ Yes□ No  Method Used: Gallons Removed: Yes □ No Cover Damaged:□ Yes□ No  plant □ Land Apply: Location
Maintainer Informatio	
Maintainer Name: Olson's Sewer Service Maintainer Address: 17638 Lyons St. NE Phone Number: 651-464-2082 Lice I hereby certify as a State of Minnesota certified S	ce Inc. Maintainer Signature:
supervised others in the performance of this job	and abservations, or un ectly



Maintenance activities must be reported to the Department within 90 days.