Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Inform	mation	Permit #: 15942 Q 3	7957
Complete in its entirety to constitute a v maintenance activities and remain on-sit	alid maintenance permit. This e for the duration of the main	permit must be completed price	
Date of Maintenance: 10-22-2N	Property I	D #:	
Property Address: 15989 Or Street Address Property Owner Name: Christia	well RDN Mo	State Zip	
Property Owner Name: Chn Stor	re Brandt		
Maintenance Perform	ed		
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Liquid Level of Tank:	x100=	el:in
Maintenance Informa Access used to remove septage: Were all covers securely replaced?	Maintenance Hole Othe Ŷes□No If No, Explain:		
Is the tank designed as a leaky? Ex. S			12 ()
Tank #1:□Yes☑No Verification Met Leaking Out:□Yes☑No Leaking In:□'	Yes No Cover Damaged:	□ Yes ◯No	
Tank #2:□Yes□ No Verification Met Leaking Out:□Yes□No Leaking In: □	hod Used:	Gallons Removed:_	
Tank #3:□Yes □ No Verification Met Leaking Out:□Yes□No Leaking In: □	hod Used: Yes □ No Cover Damaged	Gallons Removed:_	
Tank #4: ☐ Yes ☐ No Verification Met	Yes ☐ No Cover Damaged	Gallons Removed:_ :□Yes□No	
Pump Tank: ☐ Yes ☐ No Verification No Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Waste Disposal Method: ☐ Treatment	Yes ☐ No Cover Damaged	:□Yes□No	
Other remarks or Concerns:			
Maintainer Informatio Maintainer Name: Olson's Sewer Servic Maintainer Address: 17638 Lyons St. NE Phone Number: 651-464-2082 Lice	ce Inc. Maint Forest Lake, MN 55025 ense Number: L216	ainer Signature:	<i>3</i> 2

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

