Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information	tion	Permi	t#: V (00	7425378	893
Complete in its entirety to constitute a valid m maintenance activities and remain on-site for	aintenance p the duration	ermit This permit n	nust he con		
Date of Maintenance: 9/25/2024		Property ID #:			
Property Address: 4859 121 st Street Address	St. N.	WBL City	MA	55/1 tate Zip	0
Property Owner Name: Todie Sa	7				
Maintenance Performed					
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Liquid Leve Scum Level Sludge+Scu	Scum Measured: (mage of Tank:ininLiquid of the Pumped if 25%	in Level	Sludge Level:x100=	iı
Maintenance Informatio	n				
Access used to remove septage: Main Were all covers securely replaced? Yes Is the tank designed as a leaky? Ex. Seepa	□No If No, I	Explain:		ion code) Pif	~e _
Tank #1: ☐ Yes ☐ No Verification Method				s Removed: /a	250
Leaking Out: ☐ Yes ☐ No Leaking In ☐ Yes ☐					
Tank #2:□Yes□ No Verification Method	Used:		Gallon	s Removed:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	□ No Cove	er Damaged:□Yes	□No		
Tank #3: ☐ Yes ☐ No Verification Method Used:					
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes			The second secon		
Tank #4: ☐ Yes ☐ No Verification Method	1,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			s Removed:	W
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes					
Pump Tank: ☐ Yes ☐ No Verification Met		**************************************		ons Removed:_	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes					
Waste Disposal Method: ☐ Treatment pla	nt 🖰 Land A	pply: Location			
Other remarks or Concerns:					
Maintainer Information Maintainer Name: Smilie's Sewer Service Maintainer Address: P.O. Box 100 Scandie Phone Number: 651-433-3935 License I hereby certify as a State of Minnesota certified SSTS	Number: L2	428			
supervised others in the performance of this job.	ivianitamer tilat	r personally conducted t	.ne work and	made the observati	ions, or airectly

