## **Subsurface Sewage Treatment System Maintenance Permit**

Property/Owner Inforr	nation	Permit #: 🔏 i	4180937883	
Complete in its entirety to constitute a va maintenance activities and remain on-site	lid maintenance per e for the duration of	mit. This permit must be	completed prior to perfo	
Date of Maintenance: 24 oct 20	<u>/</u> ı	Property ID #:		
Property Address: 3745 Br/ Street Address	arwood A	City	55115 State Zip	
Property Owner Name: <u>Denmis</u>	Widenstr	or		
Maintenance Perform	ed			
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Liquid Level of Scum Level: _ Sludge+Scum	cum Measured: (must be of Tank:inininininininiquid Level	Sludge Level:   x100=%Slu	in
☐ Other:  Maintenance Informa	tion		annamenta de la constanta de l	
Access used to remove septage:   Were all covers securely replaced? \( \overline{L} \) Is the tank designed as a leaky? Ex. S	Yes□No If No, Ex	plain:		
Tank #1: ☐Yes ☐ No Verification Met			ons Removed: 460	
Leaking Out: ☐ Yes ☐ No Leaking In ☐				
Tank #2:□Yeş☑ No Verification Method Used:				
Leaking Out:□Yes☑No Leaking In: □				
Tank #3: ☐ Yes ☐ No Verification Met			ons Removed:	
Leaking Out: Yes No Leaking In:				
Tank #4: ☐Yes ☐ No Verification Met			ons Removed:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Pump Tank: ☐ Yes ☐ No Verification Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Waste Disposal Method: ☐ Treatmen Other remarks or Concerns:	Method Used: Yes□No Cover t plant ☐ Land Ap	Ga Damaged:□Yes□No ply: Location	allons Removed:	
	vice andia, MN 55073 ense Number: L242			
I hereby certify as a State of Minnesota certified supervised others in the performance of this job	SSTS Maintainer that I p	ersonally conducted the work a	and made the observations, or	directly



Maintenance activities must be reported to the Department within 90 days.